Maintenance Accountability Process Activity Service Level Targets and Service Levels Delivered CY 2015 - Eastern

Area: All Section: All


Activity	Α	В	С	D	F
Group - 1 Roadway Maintenance and Operations					
1A3 Shoulder Maintenance			√⊙		
1A4 Sweeping and Cleaning	√⊙				
Group - 2 Drainage Maintenance and Slope Repair					
2A1 Maintain Ditches	✓	•			
2A2 Maintain Culverts				√ ⊙	
2A3 Maintain Catch Basins and Inlets	✓	•			
2A5 Slope Repair	√ ⊙				
Group - 3 Roadside and Vegetation Management					
3A1 Litter Pickup			✓	•	
3A2 Noxious Weed Control	✓	•			
3A3 Nuisance Vegetation Control	✓			•	
3A4 Control of Vegetation Obstructions		✓	•		
3A5 Landscape Maintenance				√ ⊙	
Group - 4 Bridge and Urban Tunnel Mainten	ance and C				
4A3 Bridge Cleaning		√ ⊙			
Group - 5 Snow and Ice Control Operations					
5B1 Snow and Ice Control Operations	√ ⊙				
Group - 6 Traffic Control Maintenance and C	Operations				
6A1 Pavement Striping Maintenance	✓	•			
6A2 Raised/Recessed Pavement Marker Maint.		✓	•		
6A3 Pavement Marking Maintenance				•	✓
6A4 Regulatory Sign Maintenance			•		✓
6A5 Guide Sign Maintenance			√ ⊙		
6A6 Guidepost Maintenance				√ ⊙	
6A7 Guardrail Maintenance	√ ⊙				
6B1 Traffic Signal Systems	✓		•		
6B2 Highway Lighting Systems	√⊙				
6B3 Intelligent Transportation Systems	√⊙				
Group - 7 Rest Area Operations					
7B1 Rest Area Operations		√ ⊙			

Key


- Projected Delivery
- 2015 Service Level Delivered
- Missed Target

July 1, 2015

Activity Trend Report 1A3 - Shoulder Maintenance Region: Eastern




Activity Trend Report 1A4 - Sweeping and Cleaning Region: Eastern




Activity Trend Report 2A1 - Maintain Ditches Region: Eastern




Activity Trend Report 2A2 - Maintain Culverts Region: Eastern




Activity Trend Report 2A3 - Maintain Catch Basins and Inlets Region: Eastern




Activity Trend Report 2A5 - Slope Repair Region: Eastern



Activity Trend Report 3A1 - Litter Pickup Region: Eastern




Activity Trend Report 3A2 - Noxious Weed Control Region: Eastern




Activity Trend Report 3A3 - Nuisance Vegetation Control Region: Eastern




Activity Trend Report 3A4 - Control of Vegetation Obstructions Region: Eastern




Activity Trend Report 3A5 - Landscape Maintenance Region: Eastern




Activity Trend Report 4A1 - Bridge Deck Repair Region: Eastern




Activity Trend Report 4A2 - Structural Bridge Repair Region: Eastern




Activity Trend Report 4A2 - Structural Bridge Repair Region: Eastern



Activity Trend Report 4B1 - Movable and Floating Bridge Operations Region: Eastern




Activity Trend Report 4B2 - Keller Ferry Operations Region: Eastern




Activity Trend Report 4B3 - Urban Tunnel Systems Operation Region: Eastern



Activity Trend Report 5B1 - Snow and Ice Control Operations Region: Eastern



Activity Trend Report 6A1 - Pavement Striping Maintenance Region: Eastern



Activity Trend Report 6A2 - Raised/Recessed Pvmt Marker Maint. Region: Eastern




Activity Trend Report 6A3 - Pavement Marking Maintenance Region: Eastern




Activity Trend Report 6A4 - Regulatory Sign Maintenance Region: Eastern




Activity Trend Report 6A5 - Guide Sign Maintenance Region: Eastern



Activity Trend Report 6A6 - Guidepost Maintenance Region: Eastern




Activity Trend Report 6A7 - Guardrail Maintenance Region: Eastern



Activity Trend Report 6B1 - Traffic Signal Systems Region: Eastern



Activity Trend Report 6B2 - Highway Lighting Systems Region: Eastern



Activity Trend Report 6B3 - Intelligent Transportation Systems Region: Eastern

